

Hess Auctioneers, LLC.

1451 River Road ~ PO Box 10 ~ Marietta, PA 17547
Phone 1-866-511-2493 Fax 717-427-1665
Email ~ info@hessauctioneers.com

Blue

Auction Date	<u>4/16</u>
Stock #	<u>49448</u>
Lot #	_____

HESS REPORT SHEET

****All Trucks are For Sale AS IS, WHERE IS ***
This is NOT a Warranty!**

263,051.4

Type of Truck (Circle one): Sleeper / Daycab / Yard Jockey / Dump Box Flatbed / Other: _____

Year: 2009 Make: Sterling Model: ACTERA VIN#: AGG527

Engine: Make: CUMMINS Size: ? HP: ?

Miles: Odometer: 263,052 ECM: _____

Does the Truck- Start? Y N JumpStart Run? Y N Drive? Y N

Does the Transmission operate in all gears? Y N Emissions Deleted? Y N

Air: Loads in Normal Time? Y N (If No, How Long? _____)

Describe any major or minor fluid leaks: MOTOR

Check for coolant in the engine oil (visual inspection): OK

Pressure check cooling system at cold temperatures: (PASS/FAIL) FAIL → Automatic

Clutch Condition: Rate 1 2 3 4 5 6 7 8 9 10 _____

Verify oil pressure at idle is within OEM's specifications (=>20 psi): OK

Visually inspect blow-by. If present, check blow by with manometer at high idle. Refer to OEM's specs and record. Note Results: APPEAR OK

Check for oil in coolant (visual inspection): (PASS/FAIL) YES

Brakes Lining: Front R: 90% Front L: 90% 1st Axle R: 60% L: 60% 2nd Axle R: 60% L: 60%

Tire Tread Percentage: Front: LF 30% Rear 1: 60% Rear 2: 60% AIR AXLE

Recaps? DRIVE'S (YES) RE 20%

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Describe any Cosmetic Damage: CRACK windshield

Other Comments by Hess Inspector: _____

Mechanic: (Print Name): JACK BRANT

Mechanic: (Signature): Jack Brant Date: 1-6-21

This report is performed as a guide for our buyers. This report is not a warranty and does not in any way hold Hess Auctioneers, LLC or its agents or employees liable in any way.