

Hess Auctioneers, LLC.

1451 River Road ~ PO Box 10 ~ Marietta, PA 17547
Phone 1-866-511-2493 Fax 717-427-1665
Email ~ info@hessauctioneers.com

White

Auction Date 12/11
Stock # 47405
Lot # _____

HESS REPORT SHEET

****All Trucks are For Sale AS IS, WHERE IS ***
This is NOT a Warranty!**

87,641

Type of Truck (Circle one): Sleeper / Daycab / Yard Jockey / Dump / Box / Flatbed / Other: Recycling Truck

Year: 2008 Make: INTERNATIONAL Model: 4300 VIN#: 575815

Engine: Make: MAXXFORCE Size: 466 HP: 255 ?
7.6L

Miles: Odometer: 87,642 ECM: _____

Does the Truck- Start? Y N JumpStart Y N Run? Y N Drive? Y N

Does the Transmission operate in all gears? Y N Emissions Deleted? Y N

Air: Loads in Normal Time? Y N (If No, How Long? _____)

Describe any major or minor fluid leaks: MOTOR

Check for coolant in the engine oil (visual inspection): OK

Pressure check cooling system at cold temperatures: (PASS/FAIL)

Clutch Condition: Rate 1 2 3 4 5 6 7 8 9 10 Automatic

Verify oil pressure at idle is within OEM's specifications (=>20 psi): OK

Visually inspect blow-by. If present, check blow by with manometer at high idle. Refer to OEM's specs and record. Note Results: _____

Check for oil in coolant (visual inspection): (PASS/FAIL)

Brakes Lining: Front R: 90% Front L: 90% Axle R: 90% L: 90% Axle R: NA L: NA

Tire Tread Percentage: Front: 80% Rear 1: 20% Rear 2: NA

Recaps? DRIVE (YES)

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Describe any Cosmetic Damage: PASS SIDE OF BODY, DAMAGE.

DRIVER SEAT TORN, ① OF DRIVER SIDE, SPOT MIRROR BROKEN.

Other Comments by Hess Inspector: _____

ABS Life on. ▽ → Life ON.

ATR DRIVER POP OFF ON 700 FAST.

Mechanic: (Print Name): JACK BRANT

Mechanic: (Signature) Jack Brant Date: 11-03-20

This report is performed as a guide for our buyers. This report is not a warranty and does not in any way hold Hess Auctioneers, LLC or its agents or employees liable in any way.

DRIVER SIDE, EXHAUST HEAT SHIELD BROKEN