

Hess Auctioneers, LLC.

1451 River Road ~ PO Box 10 ~ Marietta, PA 17547
Phone 1-866-511-2493 Fax 717-427-1665
Email ~ info@hessauctioneers.com

White

Auction Date	02/12
Stock #	48481
Lot #	

HESS REPORT SHEET

****All Trucks are For Sale AS IS, WHERE IS ***
This is NOT a Warranty!**

310,855.1

Type of Truck (Circle one): Sleeper / Daycab / Yard Jockey / Dump / Box / Flatbed / Other: Service Truck

Year: 2005 Make: STERLING Model: ACTERRA VIN#: 495278

Engine: Make: CUMMINS Size: 8.3L HP: ?

Miles. Odometer: 310,855 ECM: _____

Does the Truck- Start? Y N JumpStart _____ Run? Y N Drive? Y N

Does the Transmission operate in all gears? Y N Emissions Deleted? Y N

Air: Loads in Normal Time? Y N (If No, How Long? _____)

Describe any major or minor fluid leaks: OK

Check for coolant in the engine oil (visual inspection): OK

Pressure check cooling system at cold temperatures: (PASS/FAIL)

Clutch Condition: Rate 1 2 3 4 (5) 6 7 8 9 10

Verify oil pressure at idle is within OEM's specifications (=>20 psi): OK

Visually inspect blow-by. If present, check blow by with manometer at high idle. Refer to OEM's specs and record. Note Results: Look OK

Check for oil in coolant (visual inspection): (PASS/FAIL)

Brakes Lining: Front R: 80% Front L: 80% 1st Axle R: 40% L: 40% 2nd Axle R: X L: X

Tire Tread Percentage: Front: 70% Rear 1: 70% Rear 2: X

Recaps? DRIVE Y (NO)

Cosmetic Condition: Rate 1 2 3 4 (5) 6 7 8 9 10

Describe any Cosmetic Damage: FT GRILLED BROKEN.

Other Comments by Hess Inspector: SPEEDO DON'T WORK & ODOMETER

SPEEDO & ODOMETER DON'T WORK

Mechanic: (Print Name): JACK BRANT

Mechanic: (Signature): Jack Brant Date: 7-13-20

This report is performed as a guide for our buyers. This report is not a warranty and does not in any way hold Hess Auctioneers, LLC or its agents or employees liable in any way.