

**Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

*Light Blue*

Auction Date: 4/16  
 Stock Number: 49608  
 Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*  
 \*\*\* This is NOT A WARRANTY! \*\*\*

*792726*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_  
 Year: 2011 Make: Pete Model: 386 Vin # 126918  
 Engine: Make: Cummins Model: ISX15 HP: 485  
 Odometer Reading: 792727 ECM Reading: \_\_\_\_\_

Task	Yes	No	Comments
Does the Truck Start?	X		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	X		
Does the truck have the Emission Deleted?		X	
Does the Transmission operate in all gears?	X		
Does the Air load in normal time?	X		
Are there any fluid leaks?	X		<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		X	
Is the oil pressure at idle within OEM specs?	X		
Is blow-by present?		X	MAJOR or MINOR
Do you see oil in the coolant?		X	
Pressure check the cooling system	X		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	X		Rate (1-10): <u>5</u>

Brake Lining: Front R: CASE L: SEF Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1st Axle R: 60% L: 60% 2nd Axle R: 60% L: 60%  
 Tire Tread Percentage: Front: 40% Tag Axle: \_\_\_\_\_ 1st Axle: LFI 70% LRF 70% 2nd Axle: LRF 40% RFR 20%  
 Comments: HOOD + BUMPER DAMAGE RFR > 50% RFR 50%  
 Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: PASS-SIDE windshield CRACK  
 Other Comments: \_\_\_\_\_

Inspector Print: JACK BRANT Date: 3-8-21

Inspector Signature: Jack Brant

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*