

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blue

Auction Date: 4/16
 Stock Number: 50081
 Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____
 Year: 2013 Make: VOLVO Model: VNL Vin #: HV4NCL9TH3DM137479
 Engine: Make: Cummins Model: ISX 15 450ST HP: 450
 Odometer Reading: 1122739 ECM Reading: _____

| Task | Yes | No | Comments |
|---|-------------------------------------|-------------------------------------|-------------------------------|
| Does the Truck Start? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Jump Start: YES or NO |
| Does the motor idle and run normally? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the truck have the Emission Deleted? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Does the Transmission operate in all gears? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the Air load in normal time? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Are there any fluid leaks? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | 40 PSI |
| Is blow-by present? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | MAJOR or MINOR |
| Do you see oil in the coolant? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Pressure check the cooling system | <input type="checkbox"/> | <input type="checkbox"/> | PASS or FAIL |
| Is the clutch in good operating condition? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Rate (1-10): <u>10</u> |

Brake Lining: Front R: _____ L: _____ Tag Axle R: _____ L: _____ 1st Axle R: 70% L: _____ 2nd Axle R: 70% L: 70%
 Tire Tread Percentage: Front: 70% Tag Axle: _____ 1st Axle: Replace 2nd Axle: 20%
 Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 (8) 9 10

Comments: Hood and Bumper Damage - Hood will not close correctly

Other Comments: Front Drive tires have chunks of Rubber missing, Check Engine light 13 "ON"

Inspector Print: Jeff Nolt

Date: 3-29-21

Inspector Signature: Jeff Nolt

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***